



**WELCOMES YOU TO SUGARING WITH THE *Sapling Stack Thermometer***

The *Sapling Stack Thermometer* you've just received can be used to measure the temperature of your fire while using the *Sapling*.

Simply place the thermometer on your stack just above the elbow and facing your boil. When sugaring, you are looking to achieve readings of 400 to 600 degrees. We do not recommend firing the Sapling to above 600 degrees as so measured.